Singapura paradise

ROAD REGISTER

Road from..... To..... Year 20..... 91

Length or dia of the Circle	Width at every convenient meters	Nature of existing surface	Curb Chainages	FOOT PATH				Particulars of shoulder drains and their Nos. separately for Left & Right sides	Check drains	Existence of service lines Tel. & Cable UGD line WS line etc.	Date of inspection & the initials	Remarks
				Gravel	B.S. Slab	Concrete	Other Surface					
1	2	3	4	5	6	7	8	9	10	11	12	13
160.00	5.50m	Asphalt Road Damaged mud Putty 1st Main Road	–	–	–	–	–	–	–	UGD Line		
95.00	5.50	Asphalt Road Damaged mud 2nd Main Road	–	–	–	–	–	–	–	UGD Line		
80.00	5.00	Asphalt Road Damaged 1st Cross	–	–	–	–	–	–	–	UGD Line		
75.00	5.00	〃 2nd Cross	–	–	–	–	–	–	–	UGD Line		
40.00	5.00	〃 3rd Cross	–	–	–	–	–	–	–	UGD Line	7.20/2/18	
										–		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ವಿದ್ಯಾಪೀಠ ಉಪ ವಿಭಾಗ
ಯಲಹಂಕ ವಲಯ,
ಬೃ. ಬೆಂ. ಮ. ಪಾ., ಬೆಂಗಳೂರು-97

History of Road / Lane / Circle From ..... To .....